

Carpenter Goodwin
31 Bridge St
Leominster
Herefordshire
HR6 8DU
01568 616266
www.carpentergoodwin.co.uk

Hedgetrimmer Service



Part No: 2SHS

Price: £37.50 (exc VAT) | £45.00 (inc VAT)

Specifications

Hedgetrimmer Service

- * Change spark plug
- * Change air filter

Remove guards and blow airways clear

Grease gearbox

Check idling and max revs

Check and oil

Items marked with "*" are changed as part of the service, but are chargeable separate to the Hedgetrimmer service charge.

16-10-2025 1/1