


Carpenter Goodwin 31 Bridge St Leominster Herefordshire HR6 8DU 01568 616266 www.carpentergoodwin.co.uk

Strimmer Service



Part No: 2SSS Price: £37.50 (exc VAT) | £45.00 (inc VAT)

Specifications

Strimmer Service

- * Change spark plug
- * Change air filter

Remove guards and blow airways clean

Grease gearbox

Check and lube driveshaft

Check idling and max revs

Items marked with "*" are changed as part of the service, but are chargeable separate to

the Strimmer service charge.