

S.40872 Hydraulic Lift Cover Plug



Part No: S.40872

Price: £3.95 (exc VAT) | £4.74 (inc VAT)

Specifications

S.40872 Hydraulic Lift Cover Plug - Plate Plug for 180908

3/8" NPT

(Also used to replace Plug VFH1119 Cylinder Block Plug)

OEM:

356032X1, 195567M1, 365332X1, 10650594, 12431131, 825031M1, 825031M2, 833246M1,
742207M1,

356031X1, 355547X1, 365332X1, 195567M1, 353706X1, 365572X1, 356032X1, 353756X1, 378474X1

Landini 195567M1, 10650594, 365332X1, 356032X1, 12431131

Massey Ferguson 195567M1, 365572X1, 378474X1, 365332X1, 353706X1,

833246M1, 356032X1, 825031M1, 825031M2, 353756X1, 355547X1, 356031X1, 742207M1

Landini 12431131, 195567M1, 356032X1, 10650594, 365332X1

Massey Ferguson 195567M1, 365332X1, 356032X1, 365572X1,

378474X1, 356031X1, 355547X1, 353706X1, 353756X1, 825031M1,

825031M2, 833246M1, 742207M1