

## VPB9001 - Engine Overhaul Kit



**Part No:** VPB9001

**Price:** £360.55 (exc VAT) | £432.66 (inc VAT)

### Specifications

VPB9001 - Engine Overhaul Kit

Engine overhaul kit/ A3.152 to 1935853 With finished liners With valve kit See technical information for kit contents

Kit contains:

VPA4163 Top gasket Set x 1

VPA6001 Valve kit x 1

VPB1006 Finished Liner x 3

VPB2020 Piston x 3

VPB4020 Piston Ring Set x 3

VPB6201 Con Rod Nut set x 6

VPB7000 Small end bush x 3

VPC5022 Rope seal x 2

VPC5040 Viton Seal x 1

VPC5101 Viton Seal x 1

VPC6144 Bottom gasket set x 1

OEM:

Allis Chalmers 4224057M1, 375756x1, 1476245x1, 72080017, 72080101, 72080572, 735866M1, 72080045, 78001394, 732445M1, 740407M1

Case IH / International Harvester 957E6505, 296149A1

Ford New Holland 957E6207, 957E6507, 957E6608, 957E6207A, 957E6215, 81874, 84264589, 957E6510B, 957E6505, 957E6212, 957E-6215,

81803978, 296149A1, 81717769, 81804357, 81803991, 81803866, 960E6102B, 957E6701, 81717767, 81717764, 81717827, 80505353, 505353,

81804289, 385279S2, 390655S2, 382885S2, 370664S, 34447ES2B

JCB 2130015, 2130051, 2139013, 2130064

Landini 83400, 83398, 33221327, 31431261, 375756X1, 69038, 27123, 27507, 82911, 84956, 28179, 27124, 68267, 732445M1, 81874,

U5LB0112, U5LB0012, U5LB0010, U5LT0012, 95250, 85000, 735866M1, 82136, U5LT0112, U5LT0512, 184957, 33261723, 185000, 184956,

2415344, 36883106, 36883107, 3316A031, 1447689M1, 133261723, 181512, 136883119, 141158058, 12415344, 136883106, 10095250

Leyland AJR4040, AJR4246, 7H2975

Massey Ferguson 1851747M1, 181535M1, U5LT0012, 1476245, 841521M91, 95250, 82113, 731152M1, 732445M1, 734460M91, 910002, 748007M91,

833980M1, 85000, 84956, 745819Z91, 743121V91, 735934M1, U5MK0290, 81512, 841521M92, 83398, 83400, 747187M91, 33261723, 747166M91,

740407M1, 743121M91, 745533M1, 82136, 81874, 3170514M1, 735707M91, 734460V91, 745819M91, 731761M91, 732638Z1, 731151V1, 731087M1,

731126M1, 732638M1, 732638V1, 740407V1, 735866M1, 734460Z91, 7324465M1, 731151M1, 68267, 69038, 4223519M1, 4222562M91, 4224057Z1,

731152V1, 36883106, 2414111, 375756X1, 41158058, 31431261, 2415344, 2411111, 4222817V91, 4222817M91, 31134151, 4224142M91, 4222562Z91,

355756X1, 3639947M1, 4223487M1, 4224142V91, 4223940M91, 33221319, 4224057V1, 4224057M1, 4223940V91, 31358308, 3316A031, 1447689M1, 50119,

33221327, 1476245X1, 3639495M1, 3639495Z1

Perkins 31431261, 31134151, 33221327, 33261723, 420002, 85000, 81874, 95250, U5MK0290,

36883107, 36883106, 2415344, 69038, 82136, 68267,

83400, U5LB0012, 82911, 88400, 58013, U5LT0012, 910002, 83398, 84956, 82113, 81512, 50119,  
41158058, 40360, 3316A031, 31358308

Vandervell B.7743

Volvo PH41158058, PE81512, PH31358308