

Carpenter Goodwin
31 Bridge St
Leominster
Herefordshire
HR6 8DU
01568 616266
www.carpentergoodwin.co.uk

## **VPB9504 Engine Repair Kit**



Part No: VPB9504

**Price:** £391.66 (exc VAT) | £469.99 (inc VAT)

## **Specifications**

VPB9504 Engine Repair Kit

Valve train kits are normally required during an engine overhaul, please refer to full valve train details.

Set contains:

VPA4151 Top Gasket set x 1

VPB1140 Semi finished Liner x 4

VPB2401 Piston x 4

VPB4400 Piston Ring Set x 4

VPB7010 Small end Bush x 4

5-10-2025 1/1