

Carpenter Goodwin
31 Bridge St
Leominster
Herefordshire
HR6 8DU
01568 616266
www.carpentergoodwin.co.uk

VPB9505 Engine Repair Kit



Part No: VPB9505

Price: £276.70 (exc VAT) | £332.04 (inc VAT)

Specifications

VPB9505 Engine Repair Kit

Valve train kits are normally required during an Engine overhaul please refer to full Valve Train details

Kit Contents

- 1 X VPA4028 Top gasket set
- 4 x VPB1140 Semi finished liner
- 4 x VPB2403 Piston
- 4 x VPB4400 Piston ring set
- 4 x VPB7010 Small end bush
- 1 x VPC6023 Bottom gasket set

29-08-2025 1/1