

Strimmer Service



Part No: 2SSS

Price: £37.50 (exc VAT) | £45.00 (inc VAT)

Specifications

Strimmer Service

* **Change spark plug**

* **Change air filter**

Remove guards and blow airways clean

Grease gearbox

Check and lube driveshaft

Check idling and max revs

Items marked with "*" are changed as part of the service, but are chargeable separate to

the Strimmer service charge.