

Carpenter Goodwin
31 Bridge St
Leominster
Herefordshire
HR6 8DU
01568 616266
www.carpentergoodwin.co.uk

RTC5012 Land Rover type Side Light Unit with Clear lens Landrover Defender, County, 90



Part No: RTC5012

Price: £15.95 (exc VAT) | £19.14 (inc VAT)

Specifications

RTC5012 Land Rover type Side Light Unit with Clear lens Landrover Defender, County, 90

Lucas type with screw / bolt hole mounting holes with 2 wires and Lucas L488 pattern protruding rear boot (see picture)

Replacement Bulb: RB382 (1) R382 (Pack of 10)

Optional Extras

27-07-2025 1/2

589284 Landrover type Clear Side Light Lens Defender, County 90



Part No: 589284 Price: £1.19 (exc VAT) £1.43 (inc VAT)

R382 - Stop/Flasher Pack of Ten Bulbs



Part No: R382 Price: £5.95 (exc VAT) £7.14 (inc VAT)

RB382 - Bulb 12V 21W Stop / Flasher Bulb



Part No: RB382 Price: £0.99 (exc VAT) £1.19 (inc VAT)

27-07-2025 2/2