

S.111783 Inlet Valve Guide Pk 4



Part No: S.111783

Price: £9.40 (exc VAT) | £11.28 (inc VAT)

Specifications

S.111783 Inlet Valve Guide Pk 4

Note: Valve guide needs to be reamed to correct size to accept the valve stem, after fitting.

OEM:

Landini: 3313E021

Massey Ferguson: 4223987M1

McCormick: 3313E021

Perkins: 3313E021, 3313A012

02-202218, 02/201812, 02201516, 02201812, 02202218, 1603313A012, 3313A012, 3313A012*,

3313A12, 3313E021, 3313E21, 3318A721, 375827A1, 4222142M1, 4222954M1, 4223987M1,

5200021099, 563233, 6670891, 6924947, 923726.0244, 9237260244, 923736.0745, 9237360745,

923861.0026, 9238610026, 93 164.2, 93164.2, 931642, KO3313A012, KO3313A12, P3313A012,

P3313A12, P3313E021, P3313E21, PER3313A012, U3313E021, U3313E21, U3318A721,