

TVH/50788755 Oil Temperature Warning Lamp Sensor



Part No: TVH/50788755

Price: £68.64 (exc VAT) | £82.37 (inc VAT)

Specifications

TVH/50788755 Oil Temperature Warning Lamp Sensor

OEM: AL116547, AL164451, AL178071, AL78322