

Diagnostic cable T37 Landini Transmission



Part No: VLC5922

Price: £66.78 (exc VAT) | £80.14 (inc VAT)

Specifications

To be used in conjunction with VLC5911 oscilloscope and Landini transmissions (T37)