

## VPA4508 Rocker Cover Gasket



**Part No:** VPA4508

**Price:** £3.42 (exc VAT) | £4.10 (inc VAT)

### Specifications

VPA4508 - Rocker Cover Gasket - Cork type

Thickness: 6mm

Perkins Build List:

LA (>U106654N), LD13264, 13516, 13518, 13584, 13675, 13750,13754, 13851, 13863, 13883,

13892,1 3894, 13932, 13938, 13945, 13954, 13955, 90012, 9004,7 90052, 90055, 90056,

(LA, LD, LF U106655N>) Engines with Non-Flame Ring Liners, LE22395\*, 70148, 70157, LF22801\*,

80057\*, LG70159\*, LJ50079, 70183, 80192, 80270 (\*=U106655N>)

OEM:

Allis Chalmers: 70251250, 4223924M1, 3638461M1

Case IH / International Harvester: 3118186R1

Ford New Holland: 505578

JCB: 02101749

Landini: 3681A026, 136811131, 36811131, 3681A027, 3638482M1,  
3638461M1, 3638461P1, 36811122, 36811132, 136811132

Massey Ferguson: 737225M1, 4223924M1, 36811122, 36811131,  
36811132, 3638482M1, 3681A026, 3638461M1, 746714M1

Perkins: 21826363, 36811122, 36811131, 36811132