

Carpenter Goodwin 31 Bridge St Leominster Herefordshire HR6 8DU 01568 616266 www.carpentergoodwin.co.uk

VPB4013 - Piston - 5 Ring Set



Part No: VPB4013 Price: £22.98 (exc VAT) | £27.58 (inc VAT)

Specifications

VPB4013 - Piston - 5 Ring Set

Top ring width: 2.36mm

Top ring type: External chamfer

2nd ring width: 2.35mm

- 2nd ring type: Internal chamfer
- 3rd ring width: 3.13mm
- 3rd ring type: Napier
- 4th ring width: 6.28mm
- 4th ring type: Slotted oilcontrol ring

5th ring width: 6.28mm

5th ring type: Oil control ring with coil spring

OEM: 745845Z91, 745845M91

Perkins Build List: CB, JD07757, 07977, 20074, 20172, 20680, 20858,

20869, 21383, 21493, 21608, 21708, 22075, 22117 (Models with Chrome Liners)

OEM:

Landini 141158058, 84956

Massey Ferguson 841521M92, 84956, 841521M91, 745819Z91,

743121V91, 41158058, 743121M91, 745819M91

Perkins 41158058, 84956

Volvo PH41158058