



Carpenter Goodwin
31 Bridge St
Leominster
Herefordshire
HR6 8DU
01568 616266
www.carpentergoodwin.co.uk

VPD1500 - Rotor Assembly



Part No: VPD1500

Price: £53.53 (exc VAT) | £64.24 (inc VAT)

Specifications

VPD1500 - Rotor Assembly

OEM: 827501M1, 827501M91