

VPD3201 - Fuel Lift Pump Repair Kit



Part No: VPD3201

Price: £10.91 (exc VAT) | £13.09 (inc VAT)

Specifications

Vapormatic VPD3201 - Fuel Lift Pump Repair Kit - Contains Square Gasket used on VPD3057 Lift Pump.

OEM:

Allis Chalmers 1896434M91, 71014735, 4222125M91

Case IH / International Harvester 3066610R91, 3066610R92, 3046381R91, 3046381R92, 3046382R91

Ford New Holland 3066610R92

JCB 17400401

Landini 126410009, 1852113M91, 126410087, 26410056, 1896434M91, 26410009, 26410096, 26410087, ULPR0003, ULPR0005

Massey Ferguson 4222112M91, 26410056, 26410087, 26410096, 1896434M91, 1896329M91, 4222125M91, 4222125V91, 3640785M1, 26410009, 1852113M91, 4222109M91

Perkins 26410009, 26410087, 26410096, 26410056

White Oliver 31-2755857

Other OEM:

AJR4101, 3066610R92, 17400401, 7701028825, 4222125M91, ULPR0005, 500819, 500045,
ULPR0005 ,

1896434M91, 71014735, 3066610R91, 3046381R92, 3046382R91, 3046381R91, 3066610R92,

26410056, 26410096, 26410009, ULPR0003, 26410087, 126410087, 126410009, 1852113M91

26410087, 26410096, 3640785M1, 26410009, 1852113M91, 1896434M91, 1896329M91,

4222109M91, 4222125M91, 4222125V91, 4222112M91, 31-2755857