

## VPE1153 - Water Pump



**Part No:** VPE1153

**Price:** £47.26 (exc VAT) | £56.71 (inc VAT)

### Specifications

VPE1153 - Water Pump

Impeller diameter 70mm

Front shaft diameter 16mm

Water pump repair kit VPE2011

OEM:

Case IH / International Harvester 3641338R91, 3641823R92

JCB 02130111

John Deere AHM2098

Landini 41312495, 41312154, 41312159, 3641823M91, 747542M91, 41312494, U5MW0023, U5MW0097, 141313403

Leyland AHM2098

Massey Ferguson 1476192X1, 3641823R92, U5MW0023R, 747542R91, 747542M91, 3641338R91,

4224584M1, 41312495,

41312159, 41312783, 41312967, 731280M1, 3641823M91, 3641338M91, U5MW0023, 41312154,  
41312768, 41312494, 41312786

Perkins U5MW0023, 41312154, 41312159, 41312494, 41312783, 41312786, 41312768, 41312495,  
41312055, 41312967

Other OEM: 02130111,AHM2098

## **Optional Extras**

VPE2011 - Water Pump Repair Kit



The image shows four components of the VPE2011 Water Pump Repair Kit: a long metal shaft with a nut, a black gasket, a black impeller, and a small black O-ring. A small 'INFORMATIC' logo is visible in the bottom left corner of the image area.

**Part No:**  
VPE2011

**Price:**  
£24.62 (exc  
VAT)  
£29.54 (inc  
VAT)